Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Enos Johnson AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I Site Identification, Location and Status

Site Names and ID numbers as applicable

Mine ID: 413, 465, 466, 614

Map ID: #413 - N281

#465 - N274 #466 - N275 #614 - N280

CERCLIS: NNN000908881

Navajo Abandoned Mine Land Reclamation Program:

#413 – None #465 – NA-0611 #466 – NA-0604 #614 – None

Local name / Aliases: None

Chapter and local area: #413 – Sanostee Chapter

#465 – Sanostee Chapter #466 – Sanostee Chapter #614 - Sanostee Chapter

County: San Juan **State:** New Mexico

Lat/Long: #413 - 36.4142316290 N / -108.993166535 W

#465 - 36.4181071854 N / -109.001062011 W #466 - 36.4192208466 N / -108.998704802 W #614 - 36.4130772138 N / -108.996725602 W

Nearby road and highway: IR 5010 Local Post Office: Sanostee

Surface Land Status: check one or more and provide ownership and contact information

below

Tribal Trust Land	\boxtimes	Public lands	
Private		Tribal Fee Land	
Bureau of Land Mgmt		Allotment	
State		Fee land	

Subsurface Mineral Rights:

The mineral rights ownership was identified as Indian.

Claim and operator information:

The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Enos Johnson in 1952, and R.D. Young from 1952 to 1954. No other historical ownership / lease information was identified in the EPA/AUM database.

Number of residential structures within 200 feet of mine: None

Estimated volume of mine waste onsite: #413 – None

 $#465 - 40 \text{ yd}^3$

 $\#466 - 4,630 \text{ yd}^3$

#614 – None

Part II Summary of radiological readings

Mine ID # 413

Highest gamma radiation measurement:

313,866 counts per minute (cpm)

Describe any other radiological measurements:

A total of 2,878 gamma radiation measurements were collected from the mine site, ranging from 7,668 cpm to 313,866 cpm. The measurements are represented in Figures 2 and 3.


Background Locations

Average background = 13,037 cpm

#1 11,465 cpm #2 14,605 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 2878

 Minimum:
 7668.00000

 Maximum:
 313866.00000

 Sum:
 53883985.00000

 Mean:
 18722.71890

 Median:
 15403.00000

 Standard Deviation:
 18147.35158

Highest gamma radiation measurement:

201,218 counts per minute (cpm)

Describe any other radiological measurements:

A total of 1,383 gamma radiation measurements were collected from the mine site, ranging from 11,465 cpm to 201,218 cpm. Measurements in the vicinity of the waste debris with exposed green boulders, near the rim strip were found at levels ranging from 50,000 - 150,000 cpm. The measurements are represented in Figures 4 and 5.


Background Locations

Average background = 22,989 cpm

#1 22,989 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 1383

 Minimum:
 11465.0000

 Maximum:
 201218.0000

 Sum:
 41692491.0000

 Mean:
 30146.41432

 Median:
 23684.00000

 Standard Deviation:
 20630.36538

Highest gamma radiation measurement:

157,754 counts per minute (cpm)

Describe any other radiological measurements:

A total of 2,120 gamma radiation measurements were collected from the mine site, ranging from 10,617 cpm to 157,754 cpm. Measurements in the vicinity of the waste debris slope were found at levels above 100,000 cpm. The measurements are represented in Figures 6 and 7.


Background Locations

Average background = 12,900 cpm

#1 12,900 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 2120

 Minimum:
 10617,00000

 Maximum:
 157754,00000

 Sum:
 60318896,00000

 Mean:
 28452,30943

 Median:
 20594,50000

 Standard Deviation:
 17673,07343

Highest gamma radiation measurement:

33,538 counts per minute (cpm)

Describe any other radiological measurements:

A total of 2,267 gamma radiation measurements were collected from the mine site, ranging from 10,920 cpm to 33,538 cpm. The measurements are represented in Figures 8 and 9.


Background Locations

Average background = 13,251 cpm

#1 11,469 cpm #2 15,034 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 2267

 Minimum:
 10920,00000

 Maximum:
 33538,00000

 Sum:
 38248027,00000

 Mean:
 16871,64843

 Median:
 16269,00000

 Standard Deviation:
 2892,37215

Part III Status of Reclamation and Mine Waste

Mine ID #413

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: Yes

NAMLRP Project Number: None

NAMLRP Mine features: 1 Portal

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

of any rectamation caps. Twice condition of an eaps.		
Observed reclamation work and status:		
Adits		
None		
Waste Piles		
None		
Pits		
None		

Shafts

None

Other Debris and Mine Features

None

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0611

NAMLRP Mine features: 1 Rim Strip / Pit

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclamation	work	and	status

Adits

None

Waste Piles

None

Pits

None

Shafts

None

Other Debris and Mine Features

Some slough off from existing rim strip operation leading into site with exposed green boulders; reclamation cap found in the center of the site

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: Yes

NAMLRP Project Number: NA-0604

NAMLRP Mine features: 1 Portal

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclama	tion	work	and	ctatue.
Observed	reciaina	111011	WUIK	anu	status.

Adits

None

Waste Piles

Debris slope with salt wash member, 100' x 250', with a total estimated volume of 4,630 yd³

Pits

None

Shafts

None

Other Debris and Mine Features

None

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

Not found in NAMLRP Database

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:
Adits
None
Waste Piles
None
Pits
None
Shafts
None
Other Debris and Mine Features

Enos Johnson, Mine ID #s 413, 465, 466, 614

None

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s): None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Enos Johnson mine consists of 4 mine sites with a total area of $88,595.28 \text{ m}^2$ (#413 – $18,607.07 \text{ m}^2$, #465 – $11,033.93 \text{ m}^2$, #466 – $36,889.46 \text{ m}^2$, #614 – $22,064.82 \text{ m}^2$). The mine was identified as being operational from 1952 to 1954. Historical documents showed the operator of the mine as Enos Johnson in 1952, and R.D. Young from 1952 to 1954. While operational, the mine had a total reported production volume of 1,544 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): Enos Johnson **Chapter:** Sanostee.

Decision Criteria

Is there an unreclaimed waste pile at the site? Yes

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? Yes

Is the cap/seal functionally intact? Yes

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

Waste debris found at sites #465 and #466; reclamation cap at site #465

Part VI Photos



Photo 1. Mine site #413



Photo 2. Mine site #413



Photo 3. Mine site #413



Photo 4. Mine site #465 exposed green rock with elevated readings



Photo 5. Mine site #465 reclamation cap



Photo 6. Mine site #465



Photo 7. Mine site #466 waste debris



Photo 8. Mine site #466 waste debris




Photo 9. Mine site #466



Photo 10. Mine site #614



Photo 11. Mine site #614




Photo 12. Mine site #614

Part VII Contacts Reports and Information

_
_
_
_


Information provided_____

Figure 1 - Gamma Radiation Measurements Enos Johnson (413, 465, 466, 614) Navajo Nation, Arizona



Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Mine Claim Boundaries

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)



Figure 2 - Gamma Radiation Measurements, Above Two Times Background Enos Johnson (413) Sanostee Chapter, Navajo Nation, Arizona






Figure 3 - Gamma Radiation Measurements Enos Johnson (413) Sanostee Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements


- 0 10,000
- 10,000 15,000
- 15,000 20,000
- **2**0,000 50,000
- 50,000 100,000
- > 100,000



Average background = 13,037 cpm




Figure 4 - Gamma Radiation Measurements, Above Two Times Background Enos Johnson (465) Sanostee Chapter, Navajo Nation, Arizona



Mine Claim Boundaries

Average background = 22,989 cpm

Figure 5 - Gamma Radiation Measurements Enos Johnson (465) Sanostee Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000



Inaccessible due to steep grades

→ General Direction Down-Slope


Mine Claim Boundaries

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 22,989 cpm



Figure 6 - Gamma Radiation Measurements, Above Two Times Background Enos Johnson (466) Sanostee Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements

- < 2X Backgound</p>
- > 2X Background

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 12,900 cpm








Figure 7 - Gamma Radiation Measurements Enos Johnson (466) Sanostee Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000




Mine Claim Boundaries

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 12,900 cpm



Figure 8 - Gamma Radiation Measurements, Above Two Times Background Enos Johnson (614) Sanostee Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements

- < 2X Backgound</p>
- > 2X Background

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 13,252 cpm








Figure 9 - Gamma Radiation Measurements Enos Johnson (614) Sanostee Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- **15,000 20,000**
- **2**0,000 50,000
- 50,000 100,000
- > 100,000



Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 13,252 cpm

